

Re-Entry / No-Go Re-Entry Guides

Description

Wireline Re-entry Guides are used for safe re-entry of wireline tools from the casing into the tubing string. Threaded on the top end only, they attach to the bottom end of the production string and are designed with a beveled guide and increased internal diameter. Certain tools such as tubing end locators or sample bailers are designed to be run out of the tubing to perform their tasks. The Wireline Re-entry Guide, with its internal bevel, guides the wireline or slickline tool string back into the tubing.

Adding a Single or Double brass bar stock to the Re-entry Guidewas introduced to the industry to assist in preventing unrecovered Frac balls from blocking the flow of fluids thru the tubing.

An additional innovation by Armor Tools was the development of the No-Go Re-entry Guide. This development fulfills the need for a flow control device that aids in stopping unrecovered Frac ballsand gives the well operator the ability to install recorders on the bottom side of the tubing string.

Features& Benefits

- ✓ One piece construction.
- ✓ Special clearance and L80 standard stock

and the suscence of the suscen

- ✓ Brass Bar stops are easily sheared with coil tubing
- Multiple no-go sizes to meet your well's requirements
- ✓ Custom sizes and configurations available upon request
- Available with Mule Shoe design to aidtubing deployment in deviated wells

TECHNICAL DATA			
API TUBING	OD STANDARD	O.D. SPECIAL CLEARANCE	I.D.
	in / mm	in / mm	in / mm
2-3/8 (60.3mm)	3.03 in / 76.96 mm	2.90 in / 73.66 mm	2.00 in / 50.80 mm
2-7/8 (70.3mm)	3.69 in / 93.60 mm	3.46 in / 87.88 mm	2.92 in / 74.17 mm
3-1/2 (88.9mm)	4.475 in / 113.66 mm	4.187 in / 106.35 mm	3.57 in / 90.67 mm



Re-Entry / No-Go Re-Entry Guides

Mule Shoe Re-Entry Guides / Mule Shoe No-

Go Re-Entry Guides J55 & L80

Re-Entry Guides / No-Go Re-Entry Guides J55 & L80

Re-Entry Guide: 2-3/8 EUE – Regular 1. 1. Re-Entry Guide/Mule Shoe: 2-3/8 EUE – Regular 2. Re-Entry Guide: 2-3/8 EUE - Shaved (SC) 2. Re-Entry Guide/Mule Shoe: 2-3/8 EUE – Shaved (SC) Re-Entry Guide: 2-3/8 EUE - Regular c/w 1 brass bar stop 3. 3. Re-Entry Guide/Mule Shoe: 2-3/8 EUE – Regular c/w 1 brass bar stop 4. Re-Entry Guide: 2-3/8 EUE - Regular c/w 2 brass bar stop 4. Re-Entry Guide/Mule Shoe: 2-3/8 EUE – Regular c/w 2 brass bar stop Re-Entry Guide: 2-3/8 EUE - SC c/w 1 brass bar stop 5. Re-Entry Guide/Mule Shoe: 2-3/8 EUE – SC c/w 1 brass bar stop 5. Re-Entry Guide: 2-3/8 EUE - SC c/w 2 brass bar stop 6. Re-Entry Guide/Mule Shoe: 2-3/8 EUE – SC c/w 2 brass bar stop 6. 7. Re-Entry Guide: 2-3/8 EUE - SC 1.71 No-Go Re-Entry Guide/Mule Shoe: 2-3/8 EUE – SC 1.71 No-Go 7. 8. Re-Entry Guide: 2-3/8 EUE - SC 1.71 No-Go c/w 1 brass bar stop Re-Entry Guide/Mule Shoe: 2-3/8 EUE – SC 1.71 No-Go c/w 1 brass bar stop 8. Re-Entry Guide: 2-3/8 EUE - SC 1.71 No-Go c/w 2 brass bar stop 9. Re-Entry Guide/Mule Shoe: 2-3/8 EUE – SC 1.71 No-Go c/w 2 brass bar stop 9. 10. Re-Entry Guide: 2-3/8 EUE - SC 1.79 No-Go 10. Re-Entry Guide/Mule Shoe: 2-3/8 EUE – SC 1.79 No-Go Re-Entry Guide: 2-3/8 EUE – SC 1.79 No-Go c/w 1 brass bar stop 11. Re-Entry Guide/Mule Shoe: 2-3/8 EUE - SC 1.79 No-Go c/w 1 brass bar stop 11. Re-Entry Guide: 2-3/8 EUE - SC 1.79 No-Go c/w 2 brass bar stop 12. Re-Entry Guide/Mule Shoe: 2-3/8 EUE – SC 1.79 No-Go c/w 2 brass bar stop 12. 13. Re-Entry Guide: 2-3/8 EUE - SC 1.81 No-Go Re-Entry Guide/Mule Shoe: 2-3/8 EUE - SC 1.81 No-Go 13. Re-Entry Guide: 2-3/8 EUE - SC 1.81 No-Go c/w 1 brass bar stop 14. Re-Entry Guide/Mule Shoe: 2-3/8 EUE - SC 1.81 No-Go c/w 1 brass bar stop 14. Re-Entry Guide: 2-3/8 EUE - SC 1.81 No-Go c/w 2 brass bar stop 15. Re-Entry Guide/Mule Shoe: 2-3/8 EUE - SC 1.81 No-Go c/w 2 brass bar stop 15. 16. Re-Entry Guide: 2-7/8 EUE – Regular Re-Entry Guide/Mule Shoe: 2-7/8 EUE – Regular 16. 17. Re-Entry Guide: 2-7/8 EUE – Shaved (SC) Re-Entry Guide/Mule Shoe: 2-7/8 EUE – Shaved (SC) 17. Re-Entry Guide: 2-7/8 EUE – Regular c/w 1 brass bar stop 18. Re-Entry Guide/Mule Shoe: 2-7/8 EUE – Regular c/w 1 brass bar stop 18. Re-Entry Guide: 2-7/8 EUE – Regular c/w 2 brass bar stop 19. Re-Entry Guide/Mule Shoe: 2-7/8 EUE – Regular c/w 2 brass bar stop 19. 20. Re-Entry Guide: 2-7/8 EUE - SC c/w 1 brass bar stop Re-Entry Guide/Mule Shoe: 2-7/8 EUE – SC c/w 1 brass bar stop 20. Re-Entry Guide: 2-7/8 EUE – SC c/w 2 brass bar stop 21. 21. Re-Entry Guide/Mule Shoe: 2-7/8 EUE – SC c/w 2 brass bar stop 22. Re-Entry Guide: 3-1/2 EUE - Regular Re-Entry Guide/Mule Shoe: 3-1/2 EUE – Regular 22. 23. Re-Entry Guide: 3-1/2 EUE – Shaved (SC) Re-Entry Guide/Mule Shoe: 3-1/2 EUE – Shaved (SC) 23. 24. Re-Entry Guide: 3-1/2 EUE – Regular c/w 1 brass bar stop 24. Re-Entry Guide/Mule Shoe: 3-1/2 EUE – Regular c/w 1 brass bar stop Re-Entry Guide: 3-1/2 EUE – Regular c/w 2 brass bar stop 25. Re-Entry Guide/Mule Shoe: 3-1/2 EUE – Regular c/w 2 brass bar stop 25. Re-Entry Guide: 3-1/2 EUE – SC c/w 1 brass bar stop 26. 26. Re-Entry Guide/Mule Shoe: 3-1/2 EUE – SC c/w 1 brass bar stop 27. Re-Entry Guide: 3-1/2 EUE – SC c/w 2 brass bar stop 27. Re-Entry Guide/Mule Shoe: 3-1/2 EUE – SC c/w 2 brass bar stop

All Armor Tools Brass Bar Stops are 5/32"s material EXAMPLE: Multiply Shear Force (Brass 5/32 (760psi)) for 2 points of shear = 1520psi of shear force *Custom sizes can be used upon request*